

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH QUARTER Corner of Section 34, Township 144, Range 30, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 1/22/81 found a GLO brass cap monument as set in 1930 from one  
DATE  
original bearing tree.
- left monument as found,  lowered monument,  removed monument (explain)
- On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Gay H. Stevenson 9-11-82  
SIGNATURE DATE

Registration No. 12084

- Land Surveyor,  Professional Engineer
- County Surveyor,  County Engineer

264962  
 OFFICE OF THE COUNTY RECORDER  
 County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:23 A.M. on the 14 day of Sept. A.D., 1982

County Recorder Beverly Herdink  
 By MS, Deputy

DOCUMENT NO. 264962

Statement of Evidence:

- 1875 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 8" Cedar N 79 E 202 links and 4" Cedar S 88 E 215 links.
- 1930 U.S. General Land Office dependent resurvey reestablished this corner from one original bearing tree: 10" Cedar S 88 E 215 links. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 12" Cedar S 59 W 17 links and 8" Cedar N 7 W 17 links.
- 1934 U.S. Forest Service records show the following: CCC record shows brass cap monument and the two 1930 bearing trees found.
- 1968 U.S. Forest Service records show the following: L. Martinson found the brass cap monument and the two 1930 bearing trees.
- 1981 U.S. Forest Service technician G. Brama found the corner monumented with a GLO brass cap monument in good condition up 6". The following bearing trees were found: 12" Cedar N 7 W 11.2' with blaze overgrown and 12" Cedar S 59 W 11.2' with scribe visible. One new bearing tree was marked and is shown on this certificate. Steel sign posts were set east and west of the corner. Also found original Cedar bearing tree, down and dead, at S 88 E 141.9' with flat blaze.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 On Sept. 8 I visited the corner and found items as per the 1981 USFS reports. I accepted the monument as marking the perpetuated position of the original corner based on bearing tree evidence and the 1930 GLO resurvey.