CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
·	Township 142, Range 30, 5th P.M.
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On 2/27/81 found o GLO brass cap monument as set in 1917.	
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
□ Onplaced a	
DATE	
SKETCH OF REFERENCE TIES	
14	
-N-	Nail in 9" W. Oak
	N 23 E 59.30' Scribed
Nail in 9" W. Oak	, ew
N 3 E 56.52'.	
Scribed	
%	
	Nail in 20" N. Pine
	N 81 E 139.20' Scribed
	DCI 100d
BEARINGS ARE APPROXIMATE	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	るらちょるの OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under my direct supervision.	County of Carr
1 1	I hereby certify that this document was filed in the Co. Recorders office at 10:25 A.M. on the
Nay A. Atenaison 9-15-82 SIGNATURE DATE	29 day of dept. A.D., 1982
Registration No. <u>12684</u> Mark Land Surveyor, D Professional Engineer	By M > County Recorder Deutoh Production By M > County Recorder Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 265260

Statement of Evidence:

- U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 6" Poplar N 35 E 47 links and 16" Poplar N 16 W 79 links.
- U.S. Forest Service technician W. Olson found the corner monumented with a GLO brass cap monument in good condition up 0.7'. The following bearing trees were found: None. Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 4.0' north and 4.9' south of the corner. Line was run south from the CW 1/16 corner of Sec. 30 through the 1/64 corner and extended to this corner. This fit good and rough distance measurements also agreed with the 1917 GLO resurvey record.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- On Sept. 9 I visited the corner and found items as per the 1981 USFS reports. Although no bearing tree evidence was found, the line and distance check indicate that the found monument is in the same position as when set in 1917.