

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 32, Township 141 N, Range 31 N, 5th P.M.

STATE OF MINNESOTA, County of Cass


At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 11/19/84 placed a 2 1/2 inch by 5 ft. long galvanized pipe with a 3 inch
DATE brass cap, stamped as shown, up 18 inches.

5 1/4° East declination

SKETCH OF REFERENCE TIES


not to scale



N 36°E, 24.45 ft. to a scribed
8 in. R. Oak with nail on side.

N 71°W, 24.45 ft. to a scribed
14 in. W. Oak with nail
on side.

8 ft long metal fence post with
USFS sign no. 54-9.



S 29°E, 16.75 ft. to a scribed 10 in.
R. Oak with nail on side.

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Anthony E. Kerick 12/11/84
SIGNATURE DATE

Registration No. 12266

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

280491
OFFICE OF THE REGISTER OF DEEDS

County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 9:40 A.M. on the 25 day of February A.D., 1985

Register of Deeds Christine Kayler

By MS Deputy

DOCUMENT NO. 280491

Statement of Evidence:

NORTH QUARTER CORNER OF SECTION 32, TOWNSHIP 141 NORTH,
RANGE 31 WEST OF THE 5th PRINCIPAL MERIDIAN.

1873 - The original Public Land Survey was run by P.H. Conger. A wood post was set to mark the corner and two bearing trees were recorded as accessories:

6" Birch N 74°E 3 links (1.98')
5" Pine N 73°W 7 links (4.62')

1961 - R.H. McDonald paced East from the Northwest corner of the Section and searched 6 hours found nothing.

1984 - Kerick Surveying, Inc., Bemidji, MN. Subdivided Section 32 for the U.S. Forest Service. A search was made off of the control traverse line nothing was found in the area. Corner was set Lost on line split between the Northeast and the Northwest Corner of Section 32. Set a U.S.F.S. stamped 3 inch brass capped mon. and new corner accessories that appear on this certificate.