

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 6, Township 143, Range 29, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:


On 4-6-87 found a 1" iron pipe with marked brass cap as set by
U.S.G.L.O. 1924 resurvey

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

MONUMENT MARKED:

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page. 300486

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Mary H. Stevens 6/1/87
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 4:10 P.M. on the 20 day of Oct, A.D., 1987

County Recorder Blaine Kaylor

By MS, Deputy

DOCUMENT NO. 300486

Statement of Evidence:

- 1873 - U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 9" Tamarac East 11 links and 8" Tamarac S. 27° W 8 links.
- 1924 - U. S. General Land Office dependent resurvey reestablished this corner by record distance. No evidence was found of the original corner. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 7" Maple S $62^{\circ} 45'$ E 21 links and 12" Yellow Birch S $71^{\circ} 30'$ W 82 links.
- 1987 - County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1987 - U.S. Forest Service office in Cass Lake was contacted for information and no resurvey information was found on this corner.
- 1987 - Found brass cap monument as described in 1924 in good condition. Found one 1924 BT: 18" Birch S 70° W 54.42'. Birch has scar facing corner. Did not cut open as tree is in good condition and did not want to kill it. Measured north to NE corner of Section 6 and south to 1/16 corner as set in 1924 by the GLO resurvey. Distances checked reasonably well. Accepted monument found in correct position for corner.