CERTIFICATE OF LOCATION OF GOVERNMENT CORNER closing Corner on Locations 16/17, Township 141 N, Range 30 W, 5th P.M.	
STATE OF MINNESOTA, County of	Latitude: 47° 01' 40.308" Longitude: 94° 29' 31.688"
Onfound a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 2/27/89 placed a 3/4 inch aluminum rod with point and stamped aluminum cap. (Aluminum rod is 5 feet long)	
Magnetic Decl: 5° East SKETCH OF R Not to Scale	EFERENCE TIES All distances are horizontal to nail in side of tree
8" Black Spruce S 70 W 22.16'	7" Black Spruce S 80 E 19.94'
5" Black Spruce	
Corner falls 150 feet Southerly of water of Bag Lake in Tamarack and Black Spruce swamp. 8' steel sign post South 80 degrees All trees are painted with red enamed marked with a 54-3 (bearing tree) to	nel and
Statement of evidence relative to this corner location is on back of page. 310863	
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota. David S. Landecker Date 3/10/89 Registration No. 17008	OFFICE OF THE COUNTY RECORDER County of

received the second

Statement of Evidence:

Closing Corner on Indian Reservation Boundary, Sections 16/17, Township 141 North, Range 30 West, Cass County, Minnesota

> LM-9 141-30 Bk.9 Pg.16

1873 P. H. Conger, U.S. Deputy Surveyor, noted a distance to the Reservation Boundary while running the East line of Section 17.

1917 U.S. General Land Office dependent resurvey reestablished this corner proportionally along the East line of Section 17. A wood post was set to mark the corner.

1988 a Landecker-Stevenson & Associates crew searched for the Quarter corner North of this Reservation Closing Corner. The following information was found and noted: the East Quarter of Section 17 falls in Bag Lake, therefore, it is not setable and determined lost. It was decided that a point will be set on the East line of Section 17, South of the Quarter corner monumenting this line.

1989 on February 27 a Landecker-Stevenson & Associates crew set an aluminum rod with point and stamped cap on the Indian Reservation Boundary and the Section line between Sections 16 and 17. The 1917 General Land Office wood post was not found: this corner point set was positioned by single proportion between the Northeast and Southeast corner of Section 17. New bearing trees were marked as shown and steel sign post is in place as noted on front of this certificate.