

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Reservation Line

Closing Corner _____ Corner of Section 13, Township 141 N, Range 31 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch: Latitude: 47° 02' 03.568"
 Longitude: 94° 32' 04.008"



On 6/24/88 found a 1 inch Iron Monument with Brass Cap down
DATE
18 inches

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
 Not to Scale

All distances are horizontal to nail in side of tree.



Monument is located in Forest Service Trail Number 2300 A. 4 inch by 4 inch Cedar post North 69 degrees West a distance of 15.95 feet. 8 foot sign post North 81 degrees West a distance of 14.3 feet.

All trees are painted with red enamel and marked with a 54-3 (Bearing Tree) tag.

Monument Stamped

T 141 N
 R 31 W | R 30 W
 S 13 | S 18
 LL IRB
 1917

Statement of evidence relative to this corner location is on back of page.

311071

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 (David S. Landecker)
 Date 3/24/89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 12:35 P.M. on the 27 day of March A.D., 1989

County Recorder Cloudina Kayle
 By MS, Deputy

DOCUMENT NO. 366071

Statement of Evidence:

Closing Corner on Reservation Line East Line
Section 13, Township 141 North, Range 31 West,
Cass County, Minnesota

K-L 25 141-31
Bk.5 Pg.19

1873 P.H. Conger, U.S. Deputy Surveyor, originally subdivided Section 13 while surveying under contract in Township 141 North, Range 31 West. In the process he notes the distance along the east line of Section 13 for the falling of the Leech Lake Indian Reservation Boundary. No monument was established in the process of his survey at this position.

1917 U.S. General Land Office dependent resurvey established this corner by single proportional method along the east line of Section 13 between corners that they found. These corners being the Northeast Corner of Section 13 and the Southeast Corner of Section 25 said Township. A 2 inch by 36 inch iron pipe with a marked brass cap was set to mark this corner position. The following bearing trees were marked: a 16 inch Pine North 80 degrees East a distance of 206 links; and a 8 inch Oak North 1 and 1/4 degree West a distance of 225 links.

1962 U.S. Forest Service technician McDonald found the corner monumented with a brass cap (down 8 inches). The bearing trees were gone. New bearing trees: a 7 inch Oak South 84 and 1/2 degrees West a distance of 48.0 feet; a 8 inch Oak North 54 degrees West a distance of 57.1 feet; and a 4 inch by 4 inch by 72 inch post North 69 and 1/2 degrees West a distance of 15.8 feet. Milo Stefan, USFS Surveyor, filed corner certificate in 1979 at County.

1988 on June 24 a Landecker-Stevenson & Associates crew visited the corner and found the following: The 1917 General Land Office brass cap monument down 1.5 feet; both 1962 USFS ties and post in good condition. At this time we set an 8 foot steel signpost North 81 degrees West a distance of 14.3 feet with sign 54-9; 1962 bearing trees now twin 10 inch Burr Oak North 51 degrees West a distance of 57.10 feet; and now a 9 inch Burr Oak South 85 degrees West a distance of 47.88 feet. A new bearing tree was marked: a 8 inch Burr Oak South 48 degrees West a distance of 59.30 feet.

It should be noted this certificate perpetuates the existing monument as set in the 1917 U.S. General Land Office resurvey and remonumented by the United States Forest Service in 1962. The existing monument does not represent the exact mathematical position for this corner, if it were to be established in its lost single proportionate position between the Northeast Corner and East Quarter Corner of said Section 13. It should be noted that the General Land Office resurvey used other controlling Government Corners along said Township line for their establishment of this corner. Since their survey, other controlling government corners have been found. This then causing this difference in positions noted.