



Statement of Evidence:

Standard Southeast Corner Section 36, Township  
141 North, Range 30 West, Cass County, Minnesota

Z-25 141-30  
Bk.4 Pg.10

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 22 inch Yellow Pine North 33 degrees West a distance of 25 links; and a 6 inch Maple North 69 degrees East a distance of 26 links.

1916 County Surveyor's Record Book B pages 554-558 show survey by E.B. Horst. He found post set by Curo. Horst set iron monument and witness pits North, East and South.

1925 County Surveyor's Record's show survey by John Greene. Notes show corner is 369.1 feet West of the Northeast corner of Section 1, Township 140 North, Range 30 West.

1965 U.S. Forest Service records show the following: personnel find 2 inch capped iron pipe and stump of Pine North 33 degrees West a distance of 16.5 feet. Set a 2 inch by 5 foot capped iron pipe and marked the following bearing trees: an 11 inch Norway Pine North 53 degrees West a distance of 10.9 feet; and a 9 inch Maple North 25 degrees East a distance of 35.9 feet.

1969 U.S. Forest Service surveyor, Bill Okerman, Registered Land Surveyor Number 6807, filed corner certificate on August 8, with the Cass County Recorder as certificate number 536, using the 1965 information.

1986 U.S. Forest Service crews set an aerial target over this corner position for determination of coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner. Both 1965 bearing trees were cut off.

1988 on November 10 and March 15, 1989 a Landecker-Stevenson & Associates crew visited the corner and found the following evidence: 2 inch Forest Service brass cap monument on Northwest side of 2 inch capped County iron pipe, as certified by Okerman. Both 1965 bearing trees are now 4 foot stumps. New bearing trees were marked as shown and steel sign posts are in place as noted on front of this certificate.