

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter _____ Corner of Section 35, Township 141 N, Range 29 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch: Latitude: 46° 59' 40.597"
 Longitude: 94° 18' 55.010"


On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 3/20/89 placed a 2" by 48" iron pipe with brass cap and
DATE
plastic base with magnet.

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
 Not to Scale

All distances are horizontal to nail in side of tree.



Monument is located on southerly edge of "bowl" ±125' West of swamp and ±125' East of trail.

Monument Stamped
 T 141 N R 29 W
 1/4 S26
 1/4 S35
 1989
 RLS 17008

All trees are painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

312154

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker
 Date 5-12-89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 4:04 P. M. on the 15 day of May A.D., 1989

County Recorder Claudine Kayler
 By ms Deputy

DOCUMENT NO. 312154

Statement of Evidence:

North Quarter Corner Section 35, Township 141
North, Range 29 West, Cass County, Minnesota

V-19 141-29
Bk.4 Pg.75

1873 P. H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 29 West. The notes indicate a wood post was set to mark the corner position and the following witness: a 12 inch Pine stub South 60 degrees East a distance of 46 links.

1988 on July 9 a Landecker-Stevenson & Associates crew searched for the corner. The following information was found and noted: many Pine stumps (burned), none are blazed or scribed. No evidence of post or bearing trees from original survey that fit, corner determined lost.

1989 on March 20 a Landecker-Stevenson & Associates crew returned to area and set a 2 inch by 48 inch iron pipe with brass cap and plastic base with magnet. This corner was established at the lost, single proportionate position between the Northeast and Northwest corners of said Section 35. New bearing trees were marked as shown and a steel sign post was set as noted on front of this certificate.