

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard

South Quarter _____ Corner of Section 32, Township 141 N, Range 29 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch: Latitude: 46° 58' 46.778"
 Longitude: 94° 22' 32.915"



On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 3/31/89 placed a 3/4" by 5' aluminum rod with 3/4" x 3'
DATE
fluted top and 3" aluminum tablet.

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
 Not to Scale

All distances are horizontal to nail in side of tree.



Monument Stamped
 SC
 1/4 S/32 T141N
 S 5 T140N
 1989
 RLS 17008

All trees are painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

312157

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker
 Date 5-12-89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 4:07 P.M. on the 15 day of May A.D., 1989
 County Recorder Claudine Kaylor
 By MS, Deputy
 DOCUMENT NO. 312157

Statement of Evidence:

South Quarter Corner Section 32, Township 141
North, Range 29 West, Cass County, Minnesota

Z-7 141-29
Bk.6 Pg.23

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 20 inch Tamarack North 80 degrees West a distance of 10 links; and a 11 inch Spruce North 10 degrees East a distance of 53 links.

1964 U.S. Forest Service records show the following: technician Ekstrom searched for corner, but found no evidence.

1973 Myron L. Landecker, Registered Land Surveyor Number 7452, surveyed the plat of Ondarkos Moccasin Lake Acres. In performing the survey for this plat, Mr. Landecker established a computed position for the East Quarter corner of this section at its lost position between the Southwest and Southeast corners of the section. No monument was set.

1980 Walt E. Curo, Registered Land Surveyor Number 11395, surveyed part of Government Lot 6 and part of the Southeast of the Southeast, Section 32, for the plat of Moccasin Bay. In performing his survey for this plat, Mr. Curo basically followed the same methods as described in the above survey performed by Landecker. No monument was set.

1986 U.S. Forest Service crews set an aerial target in the vicinity of this corner for the search and establishment of the true corner position. The target having coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 a Landecker-Stevenson & Associates crew searched for the corner. The following information was found and noted: position falls in an Ash swamp; no evidence of 1863 bearing trees, corner determined lost.

1989 on March 31 a Landecker-Stevenson & Associates crew set a 3/4 inch by 5 foot aluminum rod with 3/4 inch by 3 foot fluted top and 3 inch aluminum tablet. This corner was established at the lost, single proportionate position on the arc of the Tenth Standard Parallel between the Southwest and Southeast corners of said Section 32. New bearing trees were marked as shown and a steel sign post set as noted on front of this certificate.