

Statement of Evidence:

J25 Northeast corner section 13

Cor. 12,13,18 and 7 (NE Cor. Sec. 13)

- 1872 U.S. General Land Office survey set wood post for corner and the following references were noted:
White Pine 8" N 43 degrees W, 21 Links (13.86 feet)
Norway Pine 6" S 63 degrees W, 11 Links (7.26 feet)
Birch 6" S 48 degrees E, 10 Links (6.60 feet)
Fir 8" N 32 degrees E, 14 Links (9.24 feet)
- 7-2-1964 USFS corner card states Morrison and Morgan, found no post or BT's, placed a tag on east side of 7" Aspen, 1 chain west of approximate corner.
- 11-10-1965 James Ekstrom, USFS, found no evidence, road destroyed all evidence.
- 1976 BLM dependent resurvey, found no original evidence, at proportionate distance they set a copperweld, with copper cap, 6" below surface of FS road #126 and witnessed as follows:
Aluminum Post 2.5"x 28" N 65 degrees E, 37.3 feet
Aluminum Post 2.5"x 28" N 52 degrees W, 94.0 feet
- 1979 Olsen, USFS, found 1976 BLM monument.
- 7-25-1989 Personnel from Kovanen & Osufsen Inc. found 1976 BLM monument in good condition and the following witnesses:
Aluminum Post 2.5"x 28" N 55 degrees E, 37.15 feet
Aluminum Post 2.5"x 28" N 60 degrees W, 83.95 feet
we add the following witnesses:
Norway Pine 6" S 89 degrees 30 minutes W, 68.24 feet
Red Oak 12" S 68 degrees E, 41.23 feet

This position is not traceable to the original GLO corner, but accepted as corner for lack of further evidence.