CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  NORTHEAST Corner of Section 24 , Township 140 , Range 30 , 5th P.M.  STATE OF MINNESOTA, County of CASS			
		At the corner location shown on the sketch:	
		X On 8-25-81 found a 3/4" x 18" 1ra	n Pipe (down 0.3') 2.5'± West of
<u> </u>			
🗵 left monument as found, 🔲 lower	red monument, D removed monument (explain)		
□ Onplaced a			
SKETCH OF REFERENCE TIES			
4			
-N-			
4	«M		
Nail B Disc 55.33.			
North side 13" Red Oak	43.25°		
	43.25		
	Noit & Disc South side 10" Ash		
	700]		
Note: Bearings observed with compass	300		
	in the second se		
i	Noil & Disc ENE. side		
	26" Norway Pine. J.A.G.		
Statement of evidence relative to this corner loc	cation is on back of page. FILE: A-338		
I househousestife, then this decreased and the detail	324964 055105 05 THE DECISION OF DECIS		
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS —		
my direct supervision.	I hereby certify that this document was filed in		
John D. Walker 11-8-90	the Reg. of Deeds office at 2:20 PM. on the		
Registration No. 16098	Register of Deeds Claudian Konglin		
🛮 Land Surveyor, 🗀 Professional Engineer	By M, Deputy		
County Surveyor C County Engineer	DOCUMENT NO. 324964		

## Northeast corner Section 24, Township 140 North, Range 30 West

The following offices were contacted for information on this corner:
Minnesota Secretary of State
Cass County Recorder
Cass County Surveyor

- 1865 The US General Land Office field notes state that they set a post and measured to four bearing trees.
- 1919 In Book C, page 203, survey number 423, in May 1919, E.B. Horst indicates a 2"x48" iron monument at the corner. No further description or procedures are available.
- R.F. Schneider conducted a survey under contract for the DNR in the area. Schneider states an iron pipe for the corner at that time and ties were measured to the corner. Schneider gives a distance of 2564.2' to meander corner #1 in place on the south shore of Webb Lake.
- On August 25, the DNR searched for and found a 3/4" inside diameter iron pipe implace. The 3/4" iron pipe was pulled and a magnetic locator was used to search for additional monumentation but nothing else was found. Replaced the iron pipe and accepted it as the corner. Measured distance north to Meander Corner #1 proved to be 2563.89' which fits well with Schneiders 1965 distance.