CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
MEANDER CORNER. 6 Corner of Section 12 , Township 140 , Range 30 , 5 P.M.
STATE OF MINNESOTA, County of CASS
At the corner location shown on the sketch:
Is left monument as found, □ lowered monument, □ removed monument (explain)
Onplaced a
SKETCH OF REFERENCE TIES
E. V4 Sec. 12-140-30
14
Noil & Disc
Twin 8"-12" Oak.
Ment deducted with
LANCEULE BE
S. 700 E Noit B Disc
South side Triple 12"-14'-16" Oak
18. 18. 18.
The state of the s
- Acceptance of the control of the c
The state of the s
Meander
NOTE: Bearings observed with compass
File: A-338
Statement of evidence relative to this corner location is on back of page.  J.A.G.
I hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS
contained herein was prepared by me or under County of
the Reg. of Deeds office at 2:30 PM. on the
John W. Waller 11-8-90 19 day of November A.D., 19 90 SIGNATURE DATE
Registration No. 16 098    Register of Deeds Claudine A organical Engineer   Register of Deeds   Register
County Surveyor, County Engineer DOCUMENT NO. 324965
M.H.D. FORM NO. 2105

Meander Corner #6 in Section 12, Township 140 North, Range 30 West

- The following offices were contacted for information on this corner:
  Minnesota Secretary of State
  Cass County Recorder
  Cass County Surveyor
- 1865 The US General Land Office field notes state that they set a post and measured to one bearing tree.
- 1947 OGEMA POINT, a plat by Gus Holmstrom, shows a monument at the sixteenth corner but no mention is made of the type of monument or Meander Corner #6. The plat shows a distance of 112.0 feet to the water.
- 1981 On August 25, the DNR searched for and found a 2" iron pipe 1327.52 feet south of the East Quarter Corner of said Section 12. OGEMA POINT showed a distance of 1318.15 to a lot corner monument. No mention of the type of monument.
- 1982 In May, the DNR Bureau of Engineering measured a distance of 5392.16 feet between the east quarter corner of section 12 and meander corner #99 on the south shore of Webb Lake. This distance compares to a GLO distance of 5357.22 feet.

The DNR determined this corner to be lost and determined it's north-south position by proportional methods between the east quarter corner of section 12 and meander corner #99. The corners east-west position was established on an extension of the line between the east quarter corner of said section 12 and the iron pipe found at the lot corner.

The position of the meander corner falls on a very steep lake bank which prohibited setting the meander corner monument. The iron pipe 28.99 feet north and on line between the meander corner and the quarter corner north was used as a witness post.