CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter Corner of Section 5	,Township <u>134</u> , Range <u>32</u> ,5 <u>th</u> P.M.
STATE OF MINNESOTA, County of _Cass	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
X) On 12-24-91 placed a 1/2" iron pipe monument capped RLS No. 16097	
SKETCH OF R  SKETCH OF R  37.07  33.90  33.90  1/2" (ROM  PIPL BAPPED  RLS NO.16097  RLS NO.16097	SPIKE IN 10" JACK PINE  SPIKE IN SPIKE IN 8"JACK PINE  FOLD FENCES - MOSTLY DOWN  35:36"
SEC. S NOT TO SCALE	SPIKE IN  SPIKE IN  6"JACK PINE
Statement of evidence relative to this corner location is on back of page. 343234	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision  Montained herein was prepared by me or under my direct supervision  Montained No. 16,1992  Registration No. 16097  Land Surveyor, Professional Engineer	OFFICE OF THE COUNTY RECORDER  County of  I hereby certify that this document was filed in the Co. Recorders office at 2:20 f · .M. on the 24 day of March A.D., 1992  County Recorder Clauder Kaylander
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 3472 34

## Statement of Evidence:

The East Quarter Corner of Section 5, Township 134, Range 32, 5th Principal Meridian, Cass County, Minnesota, was set in 1870, under the Public Land Survey as a post with 2 bearing trees. No evidence of the Post or bearing trees was found.

A search of County records revealed no additional data.

In 1991 and 1992, while subdividing Section 5, Thomas P. Thiessen, RLS No. 16097, found an intersection of a north-south fence line with a fence line east at the position for the East Quarter Corner of Section 5. A check of distances west and south fits well, and on Dec. 12, 1991, a 1/2 inch iron pipe capped RLS No. 16097, was placed at the fence lines intersection and is accepted as the position for the East Quarter Corner of Section 5.