CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East Quarter Corner of Section 7 Township 134 Range 31 , 5th P.M.	
STATE OF MINNESOTA, County of Cass	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On June, 1992 placed a 1/2" iron pipe monument capped RLS No. 16097	
SKETCH OF REFERENCE TIES	
4	•
23'± (2)(2)	CENTERLINE OF
	(TOWNSHIP ROAD BCD
150	(OLD-ABANDONED)
41 23	
3	
	5
* /	
ne.	
PASTURE	! o rure
PASTURE & Sie	PASTURE
·	
(QQ'	
SEC. 7	
<i>5</i>	SEC. 8
<u>)</u>	
	NOT TO SCALE
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of <u>CASS</u>
my direct supervision.	I hereby certify that this document was filed in the Co. Recorders—office at 11:00 A.M. on the
from SIGNATURE APILIC 18, 1994	26 day of AORIL A.D., 1924
Registration No. 16097	County Recorder Claudine Kaylar
図 Land Surveyor, 口 Professional Engineer	By MEROFIEM ,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO357/05

Statement of Evidence:

The East Quarter Corner of Section 7, Township 134, Range 31, 5th Principal Meridian, Cass County, Minnesota, was set under the Public Land Survey as a post with two bearing trees in 1869. No trace of post or bearing trees now exsit.

On June 25, 1902, May Township issued a Supervisor's Road Order and laid out by survey a 4 rod road centered on the line between Sections 5 and 6, and Sections 7 & 8.

On April 30, 1971, May TOwnship issued a resolution to close the road running between Sections 7 & 8.

The County Surveyor's Office was contacted and corner card information was obtained.

In. 1992, while surveying the common line between Sections 7 and 8, the area of the obliterated position for the east quarter corner of Section 7 was searched at a point on the centerline of the abandoned township road equidistant from the northeast and southeast corners of Section 7. The area was hand dug and scanned with a metal detector. No corner evidence was found. A 1/2" iron pipe capped RLS No. 16097 was set at this obliterated position and is accepted as the position for the east quarter corner of Section 7/