4

Non+		OF GOVERNMENT CORNER
5TH	Principal Meridian, State of Minneso	ection 7, Township 133, Range 30  Cass
At the corner location shown on the sketch:  \[ \text{\text{In}} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
		· ·
	DATE	
SKETCH OF REFERENCE TIES		
1 4	* 	
	×	X X
		S X
N. T. S.	×	d Ave.
		43rd
	Spike in Corner Fence Post X N 45° W 59.76 feet	Senterline
_	-xxxx	Cer
	Centerline Beaver Dam Rd.	Spike in Corner Fence Post East 30.84 feet
_	deritatiine bedyer built ha.	
:		
	Solles in Rower Role	rO-
	Spike in Power Pole S 45° W 46.23 feet	Spike in Power Pole S 45° E 42.77 feet
Abstract Document #469949		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.		
I hereby certify that this document was filed in the Co. Recorders office at 9:05A.M. on the 16th day of Query A.D., 2003		
Registr	ration No. <u>17253</u>	County Recorder Kathum Morby
	Surveyor Professional Engineer	By de Deputy
Cour	nty Surveyor 🗌 County Engineer	DOCUMENT NO. 469949

Page

of & Pages

## Statement of Evidence

North 1/4, Section 7, T. 133N. R. 30W., 5th P.M.

1870 - Wood post was set for corner.

2002 — Westwood Professional Services, Inc. finds 1/2" iron piped down 0.3' capped #11865. Ties to which are shown on the front of this sheet.

Page 2 of 2 Pages