



A000640758

OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR RECORDED ON

5/24/2018 10:11:23 AM AS DOC #: A000640758 PAGES: 2 REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER
BY SF ____ Dep TX#: 146334

	Twp <u>133</u> Rge <u>29</u> Index No. <u>A.0-05.0</u>
CERTIFICATE OF LOCATION	ON OF GOVERNMENT CORNER
Northeast corner of Section 6	,Township 133 N. ,Range 29 W. , 5th P.M.
State of Minnesota, County of Cass	
At the corner location shown on the sketch:	
On 14 June 2016 found <u>a 2 inch outside diameter iron pipe, down 0.3 foot,</u> 11 feet±, east of centerline of CSAH #18 on centerline of Lynch Lake Rd.	
☐ left monument as found ☐ lowered monument ☐ removed monument (explain)	
On 27 April 2018 placed same 2 inch outside diameter iron pipe, flush, 11 feet±	
east, of centerline of CSAH #18 on centerline Lynch Lake Rd.	
SKETCH OF REFERENCE TIES	
J. J.	OT TO SCALE
 	Wooded
Yard	
V	SECTION 70
SECTION 31 16d duplex nail up 2.3 feet in N. side of a Power Pole	SECTION 32
16d_duplex_nail	16d duplex nail up 2.0 feet in S. side of a Power Pole
16d duplex nail up 2.3 feet in N. side of a Power Pole	of a Power Pole
71.60 N 73. Feet	14. E =
T134N	$\frac{N}{61.20} \frac{7}{\text{feet}}$
T133N	Centerline of Lynch Lake Road
SECTION 6	109.16 E
12566	16 feet
16d duplex nail up 1.0 foot in S side Outerline	SECTION 5
16d duplay nail	16d duplex nail up 2.3 feet in N. side
16d duplex nail up 1.0 foot in S side of 8 inch Red Oak	of 12 inch Twin Red Oak
Wooded	Open County Coordinates (Cass County South)
NOTE: All bearings are true	(Cass County South) Northing 177588.75 Easting 524380.16
Statement of evidence relative to this corner location is on the back of this page.	
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Liceps d Land Surveyor under the laws	
of the State of Minnesota.	
Terry L., Freeman, Cass County Surveyor	
Date 5/23/18 MN License No. 21367	



166.1 feet

Index No. A.0-05.0

Statement of Evidence

Northeast corner Section 6, Township 133 North, Range 29 West, 5th Principal Meridian.

E.N. Darling, General Land Office (GLO) Deputy Surveyor in the survey of the north line of Township 133 North, Aug. Range 29 West, set a post for the original corner and referenced it as follows: 1858

340 links (224.40 feet) 8" Bl. Oak 9" Bl. Oak S 54° E

N 52° W 137 links (90.42 feet) 8" Bl. Oak N 35 1/4° E 230 links (151.80 feet) 4" Aspen S 41 1/2° W 53 links (34.98 feet) Said records are on file with the Minnesota Historical Society, St. Paul, Minnesota, copies are filed with the Cass County Highway Department, Surveyor's Office (CCHD/SO).

J.W. Curo, LS 1428, Survey Record #186, Book A, page 438, 440 and 441, on file in the CCHD/SO, lists the GLO April witnesses and states "The trees appear to be gone and we pack out outfit to the SE Corner". Later "we chain 1912 17.85 ft. east to hub 3166.71 then South 21.15 feet where we drive a 3x3x36 inch oak post for the true N.W. corner of sec. 5", a Certificate of Survey was prepared and witnesses as follows:

S 9°43' W 6" Oak 49.40 feet

E.B. Horst, RLS 376, acting County Surveyor, Survey Record #400, Book C, page 127 and Curo Book 153, April

page 21, survey for a township road, on file in the CCHD/SO, states "chain out from Curo's B.T.s and find Curo's 1918 wood sec. cor. and set a 2" x 48" I.M. in its place.

J.M. Greene, Deputy County Surveyor, Survey Record #466, Book C, page 448 and Curo Book 173, page 30, on June file in the CCHD/SO, Survey of Bells Petition, states Sta. 0 = Cor 5-6-31-32 on S. line of 134-29. 1921

Survey of Road, Road Calendar B, page 51, on file with the Minnesota Historical Society, St. Paul, Minnesota, June 1921 scanned copies on file in the CCHD/SO, indicates corner at end of road.

J.M. Greene, Survey of Harrison Road, Curo Book 188, pages 25, 27 and 55, on file in the CCHD/SO, indicate May 1926 Subject Corner.

Minnesota Conservation Department, Bureau of Engineering, file A-413, on file in the Minnesota Department of Nov. 1960

Natural Resources(DNR), Baxter Office, found 2 inch pipe and witnessed as follows: 14" Oak

10" Oak S.W. 91.8 feet 8" Oak N.E. 84.1 feet

CCHD, S.A.P. 11-618-02, on file in the CCHD, found a 2 inch I.M. in centerline of roads north, south and east and Mar.

witnessed as follows: 1970

10" Birch NW 58.4 feet 6" Birch W 61.9 feet

CCHD, S.A.P. 11-618-02, on file in the CCHD, found a 2 inch I.M. in centerline of roads north, south and east and May

1971 witnessed as follows:

> 89.4 feet 6" Oak **ESF** 6" R. Oak NE 119.0 feet **Power Pole** SE 72.3 feet

B. Hippen and C. Loe, technicians, records of the CCHD/SO, found 2 inch outside diameter iron pipe, down 0.3 April foot, 11 feet, more or less, east of centerline County Road #18, on centerline of Lynch Lake Road and witnessed 1999

as follows:

N 73° W 12" Twin R. Oak **Power Pole** 71.60 feet S 78° E 109.16 feet **Power Pole** N 74° E 61.20 feet 8" R. Oak S 66° W 122.00 feet

B. Hippen, technician, records of the CCHD/SO, found P.K. nail, flush, on new overlay, 1999 witnesses all in Aug. 2000 good condition.

Dec. J. Kramer, LS 23668, Certificate of Survey in the northwest quarter of Section 5, copy on file in the CCHD/SO, 2002 indicates monument found at the subject corner.

May J.M. Leas, LS 42619, Certificate of Survey, Project No. raskp.04.002, copy on file in the CCHD/SO, indicates 2004 monument found at the subject corner.

J. Kramer, LS 23668, Certificate of Survey, Project No. BIESE0701, copy on file in the CCHD/SO, indicates May 2007 monument found at the subject corner.

J. Kramer, LS 23668, Certificate of Survey, Project No. CLARB0901, copy on file in the CCHD/SO, indicates June 2009 monument found at the subject corner.

T. Anderson, technician, CCHD, records of the CCHD/SO, found 2 inch outside diameter iron pipe, down 0.3 June 2016 foot, 11 feet, more or less, east of centerline County Road #18, on centerline of Lynch Lake Road and 1999 witnesses in good condition, removed monument prior to road construction.

B. Hippen, technician records of the CCHD/SO, reset 2 inch outside diameter iron pipe, flush, 11 feet, more or April 2018 less, east of centerline County Road #18, on centerline of Lynch Lake Road, 1999 witnesses all good. The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument recovered by CCHD/SO in 1999 is the accepted location of this corner.