

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Index No.: J-15 NORTH QUARTER Corner of Section 15, Township 133N, Range 30W, 5TH P.M.

STATE OF MINNESOTA, County of Cass


NAD 1983/2011 CASS COUNTY COORDINATES (SOUTH)
 N: 167160.11 E: 505916.81

At the corner location shown on the sketch:


- On _____ found a _____ Nothing
 (Date)
- left monument as found, lowered monument, removed monument (explain)
- On 4/12/2023 placed a 1/2" x 30" Iron Pipe W/ RLS Cap# 59285 in swamp at lost position.
 (Date)

SKETCH OF REFERENCE TIES

NOTE: POSITION FALLS IN SWAMP
 NO SUITABLE TIES IN AREA



SECTION 10



SECTION 15

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly licensed land surveyor under the laws of the state of Minnesota.

Dated this 24 day of JANUARY, 2024

By: _____
 Jared A. Spaid, Minnesota License No. 59285



A000700326

**OFFICE OF THE COUNTY RECORDER
 CASS COUNTY, MINNESOTA
 CERTIFIED, FILED, AND/OR
 RECORDED ON**

1/25/2024 1:04:53 PM

**AS DOC #: A000700326
 PAGES: 2
 REC FEES: 0.00**

BY SF _____ Dep TX#: 194550

Page 1 of 2 A000700326





Statement of Evidence:

**NORTH QUARTER CORNER SECTION 15
TOWNSHIP 133 NORTH, RANGE 30 WEST
OF THE 5TH PRINCIPAL MERIDIAN.**

- 1870 The Original Public Land Survey was run. A wooden post and two bearing tree marked the position of the Corner.**
- 2002 Bruce Grivna RLS # 17253 shows corner calculated at a lost position between the northwest and northeast section corners.**
- 2005 James Kramer RLS # 23668 indicates a found monument at corner position while conducting a survey in Section 10.**
- 2008 Jarrett Leas RLS # 42619 indicates a found monument at corner position while conducting surveys in the Northeast Quarter of the Northeast Quarter of Section 15.**
- 2023 Arro Land Surveying of Brainerd found no monument at the quarter corner position while conducting a survey in the Northwest Quarter of Section 15. There were remnants of a fence found to the north of the corner position. Based on the above surveys and monumentation found in said NW1/4, a 1/2 inch iron pipe with RLS cap # 59285 was placed at the lost position . Ties are shown on the face of this certificate.**