


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

E 1/4 20 Corner common to sections 20, 21



20

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____
Minn. Hist. Society, notes pg 117

Bearing Trees

Species	<u>Sugar</u>	<u>Lynn</u>
Diameter	<u>8"</u>	<u>10"</u>
Bearing	<u>East</u>	<u>N 81° W</u>
Distance	<u>135 links</u>	<u>39 links</u>

Original Bearing Trees Found

Species	<u>Maple</u>	
Diameter	<u>12"</u>	
Bearing	<u>East</u>	
Distance	<u>135 links</u>	

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes pg 116-117
Monument: Set 1"x 36" iron pipe with brass cap up 6", from original witness tree and marked new witnesses as follows. 1/4 S20| S21 1930

Evidence of Subsequent Corner Restoration

Year of search 11/1934 By G. Ryes, Estimator CCC
Location filed: Form 874-9
Monument: Found metal hub up 8" in good condition, corner is on S. side of a small swale and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>
Diameter	<u>12"</u>	<u>8"</u>
Bearing	<u>S 60 1/2° E</u>	<u>S 15 1/2° W</u>
Distance	<u>33 links</u>	<u>27 links</u>

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>
Diameter	<u>7"(1930)</u>	<u>11"(1930)</u>
Bearing	<u>S 10° W</u>	<u>S 66° E</u>
Distance	<u>15'</u>	<u>21'</u>

Subsequent Corner Restoration

Year surveyed 1962 By Jahnme, USFS
Location filed: USFS Book 1, page 23, 5680-11
Monument: Found corner

3/1992, G. Brama, USFS
USFS Book 1, page 23
Found GLO iron pipe with brass cap up 3" in good condition, 235'+/-, E. of Cuba Hill Rd. and witnesses as follows.
14" Maple, S 56° E, 21.8'(1930) scribe rotted
15" Maple, S 15° W, 17.8'(1930) scribe overgrown
7" Ash, N 38° W, 22.60' scribed 1/4 S20 BT, 20d spike
8" Ash, N 34° E, 21.15' scribed 1/4 S21 BT. 60d spike
Steel Sign Post, East, 2.9' with sign
7" Maple, East, 225' FSLP


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. P 9

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 20 Corner common to sections 20, 21



O = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1875
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species Sugar Lynn
 Diameter 8" 70"
 Bearing East N 81W
 Distance 135 Lks 39 Lks

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1930 By GLO
 Location filed Sec. of state
 Monument End east 81. - now 12" set 1x36" 1/4
 Wilbrass cap
S20, S21
1930

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species Maple Maple
 Diameter 12" 8"
 Bearing S 60 1/2 E S 15 1/2 W
 Distance 33 Lks 27 Lks

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____