


T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____
M.C. # 41 Corner common to sections 20, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Species	Bearing	Trees
<u>W. Pine</u>	<u>0AK</u>	
<u>40"</u>	<u>14"</u>	
<u>N15E</u>	<u>N61 1/2 W</u>	
<u>83 LKS</u>	<u>92 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1911 By JOHN Curo

Location filed COUNTY SURVEY RECORD BOOK "A" P 353-360

Monument END ORIG. B.T.S: 14" OAK N61 1/2 W 60.7', STUMP
OF 40" W. PINE N15E 54.8' SET 1 1/2 x 8" CONG
PIPE IN CONCRETE (UNDER BRIDGE)

also on microfilm - roll 115 BK 74 P. 91, 43

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1916 By E.B. Horst

microfilm - roll 105 BK 54A P. 1

End I.P. 2' above ground under bridge

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

0, P. 9

Subsequent Corner Restoration

Year surveyed 7/01 By CCSO

Location filed file # 2001.036

Monument Found PK nail, on E, 37' E
N. of Bridge deck, witness as follows:

NE Cor, NE Pier S33° E, 43.19'

NW Cor, NW Pier S28° W, 43.32'

N. Guard Rail Post N30° W, 43.96' nail in top

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - PARK'S ADDITION TO ALLAGER

KARL NOWAK 1917