


T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868

Original monument Post

Species	Bearing	Trees
<u>N. PINE</u>	<u>N. PINE</u>	
<u>24"</u>	<u>26"</u>	
<u>S 30 1/2 W</u>	<u>N 2 E</u>	
<u>71 LKS</u>	<u>194 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1971 By Dean Anderson

Location filed _____

Monument iron pipe

Evidence of Subsequent Corner Restoration

Year of search 4/1/1985 By Freeman - Marcuma

End 1" l.b. up 0.2' in line w/ G east and old fence south ± 15' W of G trail S-SE

also find all but "west" 1971 B.T.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>N. Pine</u>	<u>9"</u>	<u>NE</u>	<u>90.5'</u>
<u>N. Pine</u>	<u>15"</u>	<u>SE</u>	<u>12.7'</u>
<u>N. Pine</u>	<u>8"</u>	<u>SW</u>	<u>27.74'</u>
<u>N. Pine</u>	<u>7"</u>	<u>west</u>	<u>28.75'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By Lowell Pommerening

Found 3/4" inside diameter iron pipe down 0.1' left as found.

10-14-93 Cert Filed by Lowell Pommerening, RLS 17005, Doc. # 351919. Ties: 15" Norway Pine, N58E 40.65; 10" Norway Pine, S55W 30.65; 20" Norway Pine, S28E 13.38.

APR 2002 D. LAUDECKER

CERT of SURV SHOWS MON FOUND

Feb 2005 A. Trotter # 41002

Cert. of Survey Shows monument Found