


T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
N 14 23 Corner common to sections 14, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1868
 Original monument Post

Bearing Trees
 Species B. OAK
 Diameter 8"
 Bearing S15W
 Distance 100 LKS.

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed Dec 2002 By D. Landecker
 Location filed #17008
 Monument Cert. of Surv. shows Mon. Found.

Evidence of Subsequent Corner Restoration
 Year of search 1996 By Landecker & Assoc.
 Found 1/2" pipe by RCM 12204. Placed 2" steel with Alum cap over 1/2" pipe.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects			
<u>Poplar</u>	<u>Oak</u>	<u>Poplar</u>	<u>Poplar</u>
<u>18"</u>	<u>12"</u>	<u>18"</u>	<u>12"</u>
<u>N2°E</u>	<u>N60°E</u>	<u>S89°E</u>	<u>S2°E</u>
<u>28.10'</u>	<u>36.35'</u>	<u>40.87'</u>	<u>10.49'</u>

N-19

Subsequent Corner Restoration
 Year surveyed 1103 By Landecker & Assoc.
 Location filed _____
 Monument Found 3" sq. Alum cap marked County Surveyor at fence corner. A C&L was filed.
12" Oak N60°E, 36.14' to face
12" Poplar S2°E, 10.49' to face
8" Poplar N60°W, 17.50 to Nail
12" Oak East, 45.80 to Nail

Evidence of Subsequent Corner Restoration Found
 Year of search April 2005 By B. Grivna #17253
Cert. of Survey shows monument found.