


T. 134 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 23 Corner common to sections 13, 14, 23, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868

Original monument lost

Species	Bearing	Trees
<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>22"</u>	<u>20"</u>	<u>24"</u>
Bearing <u>N78 1/2 E</u>	<u>S48E</u>	<u>S31 1/2 W</u>
Distance <u>54 LKS</u>	<u>102 LKS</u>	<u>147 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1967 By Co Hwy Dept

Location filed Co RD # 77

Monument 2" I.P.

1971 - Dean Anderson I.P.

Evidence of Subsequent Corner Restoration

Year of search 4/11/1985 By Freeman - Marclim

End 2" I.P. in road ditch and NW 1/4 SE

R.T. 5 from 1971

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Birch</u>	<u>5"</u>	<u>NW</u>	<u>91.66'</u>
<u>KiOak</u>	<u>12"</u>	<u>NE</u>	<u>73.91'</u>
<u>W. oak</u>	<u>6"</u>	<u>SE</u>	<u>97.70'</u>

1971 trees

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>6" w.oak</u>	<u>new 12"</u>	<u>S50°E</u>	<u>97.70'</u>
<u>KiOak</u>	<u>10"</u>	<u>N40°E</u>	<u>95.85'</u>
<u>Electric Junction Box</u>	<u>"U4414"</u>	<u>N19W</u>	<u>21.65'</u>

new nail inside

N-21

Subsequent Corner Restoration

Year surveyed 1996 By Landecker & Assoc.

Location filed \_\_\_\_\_

Monument Set 2" steel tube with Alum cap at RCM worksheet position.

<u>8" Poplar</u>	<u>N24°E</u>	<u>52.13'</u>
<u>12" Oak</u>	<u>N39°E</u>	<u>95.38'</u>
<u>18" Poplar</u>	<u>S74°E</u>	<u>158.93'</u>
<u>18" Oak</u>	<u>S52°E</u>	<u>97.48'</u>

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

APR 2002 D. LANDECKER

CERT of SVY SHOWS MON FOUND

April 2005 B. Grivna #17253

Cert. of survey shows monument found

1/2003 - Landecker & Assoc. found Alum cap, 15' E S & 4' E W of fence corner and 1996 witnesses. A Cert was filed.