


T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 5 Corner common to sections 4, 5 AND 32, 33 - 135 - 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument POST

Bearing Trees	
Species <u>ASPEN</u>	<u>ASPEN</u>
Diameter <u>6"</u>	<u>5"</u>
Bearing <u>N76W</u>	<u>S62W</u>
Distance <u>50 LKS.</u>	<u>63 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1993 Oct By Thomas Thiessen

Found chunk of metal 5' north of County Road

P.I. Removed.

Oct, 1993 placed 1/2" x 4" long pipe capped RLS #16097

4-26-94 Dec. Filed by Thomas Thiessen, RLS #16097,

Doc. #357100

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

<u>Aspen</u>	<u>Red Oak</u>	<u>Aspen</u>
<u>5"</u>	<u>8"</u>	<u>5"</u>
<u>18.83</u>	<u>71.71</u>	<u>50.00</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Jan 1904 By _____

Twp rd order shows no survey

Feb 1914, Twp rd order shows no survey