


T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 14 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>OAK</u>	<u>ASPEN</u>
Diameter <u>4"</u>	<u>8"</u>
Bearing <u>N12E</u>	<u>S45E</u>
Distance <u>14 LKS.</u>	<u>10 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/14/86 By Freeman - Glen Williams  
 Location filed Backhoe  
 Monument dug in center of road & fence south  
10' E-W, 9' N-S, 4 1/2' deep  
2.5' - road top - gravel/rocks, 2 natural -  
sandy - rocky - clay numerous leadstones & rock.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____
Diameter	<u>found nothing</u>
Bearing	<u>SET 2" x 18" TELESPAR Mon WITH</u>
Distance	<u>ALUM. CAP</u>

Bearing Trees, Reference Objects

RED OAK	IRONWOOD	BURR OAK	Pur. Pole
<u>10"</u>	<u>4"</u>	<u>9"</u>	
<u>N 49 E</u>	<u>S 45 E</u>	<u>S 22 W</u>	<u>N 52 W</u>
<u>117.95</u>	<u>85.67</u>	<u>70.23</u>	<u>54.60</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1-31-90 Cert. Filed by Walter Curo, RL5 11395  
Doc. #318240

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_