


T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/4 R6 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. PINE</u>	_____	_____
Diameter	<u>20"</u>	_____	_____
Bearing	<u>S 10 W</u>	_____	_____
Distance	<u>90 LKS.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/19/86 By Freeman, Glen Williams
 Location filed Buckhoe
 Monument dug in center of road & fence east
dug 9' E-W 12' N-S 3.5' deep
2.5' gravel-top's fill, 1' natural clay-loam
9/18/86 set cast iron pipe down 10"

Evidence of Subsequent Corner Restoration

Year of search July 1905 By _____
Traced order shows no survey

Bearing Trees, Reference Objects

Species	<u>SACK PINE</u>	<u>NOR. PINE</u>	<u>PWR. POLE</u>
Diameter	<u>3"</u>	<u>18</u>	_____
Bearing	<u>N 26 W</u>	<u>S 24 W</u>	<u>S 15 E</u>
Distance	<u>65.25</u>	<u>91.70</u>	<u>129.40</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
L-22-90 Cert. Filed by Walter Curro, RLS 11395
Doc. # 317971