


T. 134 R. 32 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 1 Corner common to sections 1 AND 36-135-32



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1858  
Original monument lost

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species SP. PINE SP. PINE  
Diameter 6" 10"  
Bearing N 69 E N 41 W  
Distance 38 LKS. 15 LKS.

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 9/29/85 By Surveyors Office  
Find 1 1/2" l.p. down 0.75'; 3.5' S. of C E-W Rd  
5.5' W. of fence S.  
Certificate-Curo - 1987 - Doc # 297520

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
Red oak Jack Pine Red oak CFP  
Twin 12" 7" 11"  
N 20° W N 39° E S 58° W S 10° E  
58.05' 59.80' 78.26' 32.07'  
Survey marker sign North 33.0'

Subsequent Corner Restoration  
Year surveyed 5/2001 By CCSO  
Location filed CCSO  
Monument Found 1.5" ODIP, down 1.0',  
3' S. of E 96th St. Also 1985 witness  
NW. Add the following:

10" P. Oak N 30° E, 70.45 dbl. hd. nail  
10" W. Oak S 11° E, 68.48 dbl. hd. nail

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - W & H Curo - 1987  
Doc. # 297520

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_