


Index No. G5

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____
E 1/4 7 Corner common to sections 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument lost

Bearing Trees		
Species	<u>BL. PINE</u>	<u>N. PINE</u>
Diameter	<u>6"</u>	<u>16"</u>
Bearing	<u>S 1/6 E</u>	<u>S 29 W</u>
Distance	<u>215 LKS.</u>	<u>356 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 3/14/92 By Thomas Thiessen

Location filed Cert. Filed Doc # 343242

Monument Set 1/2" iron pipe monument capped
RLS 16097

Bearing Trees, Reference Objects			
Species	<u>Oak</u>	<u>Oak</u>	<u>Oak</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>12"</u>
Bearing	<u>SW</u>	<u>South</u>	<u>SE</u>
Distance	<u>58.97'</u>	<u>49.66'</u>	<u>70.85'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

11-24-92 Cert. Filed by Thomas Thiessen
RLS 16097 Doc # 343242

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____