


T. 135 R. 29 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 5 Corner common to sections 5 AND 32-136-29



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1858
 Original monument POST

Species	Bearing	Trees
<u>PINE</u>	<u>PINE</u>	
Diameter <u>8"</u>	<u>8"</u>	
Bearing <u>S45W</u>	<u>N57W</u>	
Distance <u>4 LKS.</u>	<u>15 LKS.</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 9/21/1977 By M. LANDECKER
 Location filed LANDECKER RECORD INDEX #6
 Monument SET 3/4" PIPE BY LAND LINES & CALCULATIONS
SE QUADRANT OF "T" TRAIL INTERSECTION

Species	Bearing	Trees, Reference Objects
<u>R. PINE</u>	<u>V. PINE</u>	<u>R. PINE</u>
Diameter <u>18"</u>	<u>20"</u>	<u>16"</u>
Bearing <u>SW</u>	<u>SE</u>	<u>SSE</u>
Distance <u>45.0</u>	<u>36.5</u>	<u>69.35</u>
<u>DBL BLAZE</u>	<u>DBL BLAZE</u>	<u>DBL BLAZE</u>

Evidence of Subsequent Corner Restoration
 Year of search 1999 By Landecker & Assoc.
Cert. of Survey indicates monument found.
Oct. 1903 w.H. Hall III
Trwp rd order shows survey

Bearing Trees, Reference Objects

A-7 Subsequent Corner Restoration
 Year surveyed 3/2001 By CCSO
 Location filed CCSO
 Monument Found CIM, down 0.7',
6' S. of E 16th Ave.

6" N. Pine, N34°E, 93.91' *
8" N. Pine, S53°E, 53.32 *
10" N. Pine, S24°W, 41.89 *
* distance to dbl head nail

Nov. 2002 O. Landecker #17008
Cert. of Svy. shows mon. found

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Mar. 14, 1991 Cert. filed by O. Landecker
RLS 17008 Doc. # 336117