


T. 135 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>Aspen</u>	
Diameter <u>8"</u>	<u>6"</u>	
Bearing <u>N61W</u>	<u>S45 1/2 W</u>	
Distance <u>359 LKS</u>	<u>289 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CURRO
Location filed COUNTY SURVEY RECORD BOOK "B" P. 369-376
Monument FOUND STUMPS OF BOTH OLD GOVT BITS. SET 2x48" IRON

Evidence of Subsequent Corner Restoration

Year of search 1982 By _____
Survey Technician T. Freeman & Forester D. Marcum. Found 2" iron with cap ± 8' S.W. OF P.I. OF roads EW & N-S.

also on microfilm - vol 1105 BK 56 P. 31, 34

1971 - Co Hwy Dept - Co RD # 29 2" I.M. in place 4' west and 7.7' South of P.I. roads

Bearing Trees, Reference Objects

Species	J. Pine	J. Pine	J. Pine	J. Pine
Diameter	<u>12"</u>	<u>12"</u>	<u>STUMP</u>	<u>10"</u>
Bearing	<u>N61-50E</u>	<u>N48W</u>	<u>S27-05W</u>	<u>S60E</u>
Distance	<u>38.20</u>	<u>67.10'</u>	<u>33.20'</u>	<u>28.70'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

E-5

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument Oct. 1903 W. H. Hallett
Twp rd order shows survey

Year of search 1999 By Landecker & Assoc.
Cert. of Survey indicates monument found.

2000 - CC50

Found in place 2" I.M flush w/ bit as of 6/7/00. (Overlay summer 2000 scheduled) Located 7'S & C.R. 29 and 4' W of & C.R. 78 and & Jacob's Rd.

REF. TIES:

<u>10" R. Oak</u>	<u>N 36° E</u>	<u>134.27'</u>
<u>13" W. Pine</u>	<u>S 60° E</u>	<u>124.87' (A.W. Lind)</u>
<u>11" Balsam</u>	<u>S 26° W</u>	<u>128.31'</u>
<u>P. Pole</u>	<u>N 32° W</u>	<u>74.95' (TAG)</u>

* distance pulled to dbl. hd nail

Aug. 2000 - re-est. cor. by setting a MAG NAIL from ties - POST. CONSTR.

March 2003 Landecker Sketch
Sketch shows mon. found

Nov. 1986 D Landecker #17008
Cert of survey shows monument found