


Index No. E 15

CASS COUNTY LAND CORNER RECORD

T. 135 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 10 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>ASPEN</u>	<u>OAK</u>	_____
Diameter	<u>14"</u>	<u>10"</u>	_____
Bearing	<u>NORTH</u>	<u>S18W</u>	_____
Distance	<u>10 LKS.</u>	<u>12 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 2000 By CCSO  
Found in place 2" I.P. w/ 2 1/2" plumbers cap.  
located 3'S & C.R. 29 and 7' W of North  
fence line and 3' W of south fence line.  
AUG. 2000 - RESET A MAG NAIL POST CONSTR.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>P. Pole</u>	<u>Maple</u>
<u>20"</u>	<u>14"</u>	_____
<u>N 5° E</u>	<u>N 40° E</u>	<u>S 12° W</u>
<u>119.14'</u>	<u>80.25'</u>	<u>147.69'</u>

(TAG)

\*distance to dbl. hd. nail

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search Nov. 1920 By \_\_\_\_\_  
Inspected order shows no survey

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_