


T. 135 R. 30 M. 5TH Coordinates: X NE 24 Y 13, 24 AND 18, 19-135-29  
Corner common to sections 13, 24 AND 18, 19-135-29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trass	
BIRCH	BIRCH	PINE	PINE
Diameter 6"	8"	8"	30"
Bearing S 75 E	N 21 W	S 57 W	N 43 E
Distance 18 LKS.	67 LKS.	28 LKS.	100 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By EL TUSLER  
Location filed COUNTY BOOK "C" P. 377  
Monument SET I.M.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By B. Griner  
Sec. Worksheet shows 2" pipe found  
in place  
Nov. 1919 Twp rd order shows no survey

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

N-25

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Apr. 2003 B. Griner #17253  
Cert. of sup. shows Mon. found  
Oct. 1903. W.H. Hallett  
Twp rd order shows survey

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_