


T. 135 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869

Original monument POST

Species	Bearing	Trees
<u>ASPEN</u>	<u>ELM</u>	<u>OAK</u>
<u>20"</u>	<u>4"</u>	<u>4"</u>
<u>S78E</u>	<u>S71W</u>	<u>N42W</u>
<u>36 LKS</u>	<u>4 LKS.</u>	<u>20 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E.B. HORST

Location filed COUNTY RESURVEY "E-33"

Monument IRON MONUMENT, GOVT BITS

1921, E.B. HORST, COUNTY BOOK "C" P. 412 SET 2x48" I.M.

From NE, SW & SE STUMPS.

Species	Bearing	Trees, Reference Objects
<u>OAK</u>	<u>ASPEN</u>	<u>ASPEN</u>
<u>10"</u>	<u>4"</u>	<u>4"</u>
<u>NW</u>	<u>SW</u>	<u>SE</u>
<u>43.2'</u>	<u>43.3'</u>	<u>29.5'</u>

Evidence of Subsequent Corner Restoration

Year of search 1999 By DNR J. Walker

Certificate of survey indicates

Iron monument found in place. 1-1/2"

IRON PIPE, DOWN 6" ON E EXTENSION FROM

WEST & WEST EDGE OF ROAD TO NORTH

CERT. OF LOCATION, MAY '99, DOC # 412424

Species	Bearing	Trees, Reference Objects
<u>GATE BRACE POST</u>	<u>GATE POST</u>	<u>POWER POLE</u>
<u>NAIL & RP</u>	<u>NAIL & RP</u>	<u>NAIL & RP</u>
<u>N86°E</u>	<u>S60°E</u>	<u>S17°E</u>
<u>51.84</u>	<u>57.78</u>	<u>32.44</u>

V-21 Subsequent Corner Restoration

Year surveyed 6/2005 By CCSO

Location filed #2001.024

Monument Found 2" OD IP, down 0.6,

3'±N and 8'±W of 'E PT Co. Rd.

#107, DNR P. Pole witness has been

cut off and replaced witness:

P. Pole S18°E, 33.40'

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
