


T. 135 R. 30 M. 5TH Coordinates: X _____ Y _____
E1436 Corner common to sections 36 AND 31-135-29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>PINE</u>	<u>ASPEN</u>	_____
Diameter	<u>9"</u>	<u>12"</u>	_____
Bearing	<u>S81E</u>	<u>N30 1/2 W</u>	_____
Distance	<u>153 LKS.</u>	<u>173 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search JUNE 1997 By M/DNR J. WALKER
SET DNR SURVEY MARKER IN CENTERLINE
OF WESTERLY DITCH OF NORTH-SOUTH ROAD
CERT. OF LOCATION MAY '99 DOC # 412428

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>ELM</u>	<u>ASH</u>	<u>RED OAK</u>	<u>21 ±</u>
<u>14"</u>	<u>3"</u>	<u>12"</u>	<u>WEST</u>
<u>S68°W</u>	<u>N64°W</u>	<u>S48°E</u>	<u>OF GRAVEL</u>
<u>54.77</u>	<u>31.25</u>	<u>84.11</u>	<u>E</u>

X-25

Subsequent Corner Restoration

Year surveyed 7/2003 By _____
Location filed #2001.024
Monument Found DNR Survey Marker in
ditch, 21 ± W. of E Co. Rd #107,
29 ± N. of driveway, DNR witnesses
NW & SE are good, add:
7" W. Oak N70°E, 70.36' *
*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By Landecker & Assoc.
Cert. of Survey indicates T.M.
set, marked by license no. 17008.
Oct. 1903 W.H. Hallett
Twpcrd order shows survey