


Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 8 Corner common to sections 4, 5, 8, 9



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1870  
Original monument Post

Species	Bearing	Trees	Species	Trees
<u>ELM</u>	<u>ASPN</u>	<u>ELM</u>	<u>ELM</u>	<u>ELM</u>
Diameter <u>11"</u>	<u>7"</u>	<u>8"</u>	<u>14"</u>	
Bearing <u>N35E</u>	<u>S47E</u>	<u>S28W</u>	<u>N43 1/2 W</u>	
Distance <u>31 LKS.</u>	<u>119 LKS.</u>	<u>62 LKS.</u>	<u>211 LKS.</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed 1999 By CCSO  
Location filed CCSO Top file  
Monument Found 1 1/4" OD IP down 0.7'  
in E. Co. Rd. #103, 8' East of  
E. 61st Ave.

**Bearing Trees, Reference Objects**

Species	Bearing	Trees	Reference Objects
<u>T. Red</u>	<u>S48°W</u>	<u>Sign Post</u>	<u>Elec. Pad</u>
Diameter _____	<u>SW Cor.</u>	<u>"X" in Conc.</u>	<u>"X" in Conc.</u>
Bearing <u>N65°E</u>	<u>S48°W</u>	<u>S30°E</u>	<u>N40°W</u>
Distance <u>68.50*</u>	<u>44.21</u>	<u>56.76</u>	<u>44.16</u>

\*distance to double head nail

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Feb 1901; Twp Rd order shows no survey

June 1901 P.A. Bean  
Twp Rd order shows corner

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_