


T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____
N 1/4 1 Corner common to sections 1 AND 36-136-32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species LYNN LYNN
Diameter 9" 14"
Bearing N 74 E N 13 W
Distance 46 LKS. 4 RLKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1985 8/26 By Terry Freeman
State Hwy Dept in 1957 assumed cor. at intersection
of Rd 1 & Fwy N. assumed cor. 39.45' S. of a (new)
1986 - set 2x36" telescope monument at Hwy
Dept location
1987 - Curro - Certificate - Doc # 297165

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

N. Pine Burr Oak N. Pine
7" 20" 7"
N 41° W S 51° W S 62° E
117.38' 38.80' 36.22'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curro - 1987
Doc. # 297165
Dec. 1901; Insp rd order shows no survey