


T. 135 R. 32 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 28 Corner common to sections 21, 22, 27, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866

Original monument lost

Species	Bearing	Trees
<u>Aspen</u>	<u>TAM</u>	<u>TAM</u>
Diameter <u>10"</u>	<u>8"</u>	<u>10"</u>
Bearing <u>S72E</u>	<u>N37E</u>	<u>N4W</u>
Distance <u>34 LKS.</u>	<u>69 LKS.</u>	<u>36 LKS.</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By E.B. Horst

Location filed COUNTY BOOK "C" P. 78

Monument SET 50 d SAKE, SET 1 1/2 x 48" I.M  
1915, R. BRYANT, BOOK "C" P. 572 FND. CORNER.  
also on microfilm - roll 115 BK 71 P. 84

Species	Bearing	Trees, Reference Objects
<u>J. Pine</u>	<u>Poplar</u>	
Diameter <u>5"</u>	<u>5"</u>	
Bearing <u>N 11-30 E</u>	<u>S 25-25 E</u>	
Distance <u>54'</u>	<u>46.2'</u>	

Evidence of Subsequent Corner Restoration

Year of search 1915 By E.B. Horst

microfilm - roll 115 BK 71 P. 124-125  
set 50 d spike at corner of road  
same trees  
P. 131-132 set I.M.

Species	Bearing	Trees, Reference Objects
_____	_____	
_____	_____	
_____	_____	

R-13

Subsequent Corner Restoration

Year surveyed 1985 By Freeman - Marcus

Location filed \_\_\_\_\_

Monument Fnd 1 1/2" 1 1/2" bent SE

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Walt Curo - 1985  
Doc. # 286247  
replace 1 1/2" w/ 2" sq. steel monument with  
stamped aluminum cap  
5" Poplar N 43 W 82.30'  
3" J. Pine N 30 E 53.38'  
13" Poplar S 26 W 50.60'  
Survey marker sign N 45 W 2'

2000 July - Fnd. in place; 2" sq. telapar  
monument w/ cap - stamped RLS 11395  
Located 10' N of approx. P.I. of road,  
and 26' ± E of E Rd.

REF. TIES:

<u>8" J. Pine</u>	<u>N 30° E</u>	<u>53.38'</u>
<u>CFP</u>	<u>S 86° E</u>	<u>38.27'</u>
<u>13" Poplar</u>	<u>S 26° W</u>	<u>50.60' (fnd. nail)</u>
<u>SVY MKR. SIGN</u>	<u>N 45° W</u>	<u>2.0'</u>

\* distance to dbl. hd. nail

- Corner GPS 11/5/02 CCSO  
Alum cap telapar, RLS 11395 near E PI