


T. 136 R. 29 M. 5th Coordinates: X _____ Y _____
M.C. # 27 Corner common to sections 20, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Bearing Trees

Species	Bearing	Distance
<u>N. Pine</u>	<u>N. Pine</u>	
<u>18"</u>	<u>14"</u>	
<u>S6E</u>	<u>N59W</u>	
<u>47 LKS</u>	<u>52 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1909 By John Luro
Location filed COUNTY SURVEY RECORD BOOK 'A' P571-576
Monument END OLD GOVT B.T.: 18" N. Pine S6E 47 LKS
1916 - E.B. BEST END OLD GOVT B.T.: 18" N. Pine S6E
47 LKS SET R498" IRON
also on MICROFILM - roll 115 BK84 P. 8

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. Pine</u>	<u>N. Pine</u>	
<u>4"</u>	<u>22"</u>	
<u>N43-30W</u>	<u>S6E</u>	
<u>31.30'</u>	<u>31.02'</u>	

1916 ties

Evidence of Subsequent Corner Restoration

Year of search 1/2003 By Landecker & Assoc.
Found 1/4" threaded iron pipe, up 0.5'
11' ± W. of Lake shore
Certificate filed.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Oak</u>	<u>N. Pine</u>	<u>N. Pine</u>
<u>12"</u>	<u>15"</u>	<u>15"</u>
<u>N10°W</u>	<u>S28°E</u>	<u>N38°W</u>
<u>60.27'</u>	<u>60.17'</u>	<u>28.91'</u>

R, 5-6

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared
Filed at CCRO document # 462469

By RLS #17008
Date 2/14/03