


T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____

M.C. # 17 Corner common to sections 33, 34

SOUTH EAST SIDE MAYO LAKE



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. PINE</u>	<u>TAM.</u>	_____
Diameter	<u>18"</u>	<u>6"</u>	_____
Bearing	<u>S77E</u>	<u>S41W</u>	_____
Distance	<u>222 LKS</u>	<u>1556 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1953 By DEAN ANDERSON
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 6/30/81 By D. LANDECKER
FOUND 2" IRON PIPE W/ OBLONG CAP. 2'±
UP, LYING DOWN? STRAIGHTENED UP. CLARENCE
HERTIG TESTIMONY ON EXISTING TIES. COR. IS
IN THE ALDER MARSH 25' WEST OF EDGE
1953 18" R.OAK S20E 82.60

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>R.OAK</u>	<u>ASPEN</u>	<u>BIRCH</u>	<u>BORR OAK</u>
<u>14"</u>	<u>5"</u>	<u>4"</u>	<u>8"</u>
<u>S75E</u>	<u>S45E</u>	<u>S30E</u>	<u>S25E</u>
<u>48.78</u>	<u>32.95</u>	<u>37.32</u>	<u>72.80</u>

DR. BLZD, DISC'S APPROX 3' UP IN BLAZES

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____