


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 136 R. 32 M. 514 Coordinates: X _____ Y _____
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1866
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing Trees			
	BL. Pine	BL. Pine	BL. Pine	BL. Pine
Diameter	<u>5"</u>	<u>10"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>S17 1/2 W</u>	<u>S76 E</u>	<u>N89 E</u>	<u>N4 W</u>
Distance	<u>160 LKS</u>	<u>312 LKS</u>	<u>202 LKS</u>	<u>94 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 10/1904 By W. Hallett
 Location filed Twp Road Orders
 Monument Surveyors Report shows Road on East line sec. 32.

Evidence of Subsequent Corner Restoration
 Year of search 2000 By CCSO
Find. incl. 1 3/4" ODIP flush w/grad. Located E of old rd. grade, 26'± W of E Ditch, and 34'± E of N/S fence line.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>P. Pole</u>	<u>6"</u>	<u>N 74° W</u>	<u>35.75'</u>
<u>J. Pine</u>	<u>16"</u>	<u>S 24° W</u>	<u>26.53'</u>
<u>J. Pine</u>	<u>10"</u>	<u>N 48° E</u>	<u>48.43'</u>
<u>J. Pine</u>	<u>10"</u>	<u>S 28° E</u>	<u>19.65'</u>

*distance to dbl. hd. nail

V-9 Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Feb. 1905 - Twp rd order shows no survey

Remuneration certificate prepared _____
 Filed at _____

By _____
 Date _____