


T. 137 R. 29 M. 5th Coordinates: X _____ Y _____
E 1/4 9 Corner common to sections 9, 10



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument POST

Bearing Trees
 Species SPRUCE SPRUCE
 Diameter 10" 8"
 Bearing S67E S87W
 Distance 0 LKS 25 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1904 By W.H. Hallett
 Location filed Tap Rd Orders and Tap file
 Monument Surveyor's Report indicates witnesses.

Evidence of Subsequent Corner Restoration
 Year of search 9-25-02 By D. Landecker #17008
(CRO # A000488015
4" Flat bar with broken 4" cross (CIM
lying on top)

Bearing Trees, Reference Objects
 Species W. Oak
 Diameter 8"
 Bearing N51°30'W
 Distance 47 LKS
(31.0')

Bearing Trees, Reference Objects

RED OAK	Fence Post	ASPEN	Fence Post
16"		10"	
N 23° E	N 66° E	S 72° E	S 54° E
183.96'	25.71'	65.23'	24.26'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____