


Index No. N 21

CASS COUNTY LAND CORNER RECORD

T. 137 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees		
Species	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>11"</u>	<u>10"</u>	<u>6"</u>
Bearing	<u>S83E</u>	<u>N81 1/2 E</u>	<u>S3W</u>
Distance	<u>129 LKS</u>	<u>130 LKS</u>	<u>162 LKS</u>

Original Bearing Trees Found		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1920 By MORRIS
Location filed COUNTY BOOK 2 P. 567
Monument FIND STAKE AND ALL 3 GOVT B.T STUMPS.

Evidence of Subsequent Corner Restoration

Year of search 7/2003 By CCSO
Found 1 1/4" ODIP, down 1.9', bent, straighten and raise to 0.6' below surface of road, 6'± E. of & 52nd Ave., 1'± N. of fence to East. (GPS Position)

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Elm</u>	<u>6"</u>	<u>N68°W</u>	<u>42.55*</u>
<u>Aspen</u>	<u>4"</u>	<u>S64°W</u>	<u>36.09*</u>
<u>Fence Cor</u>	<u>P. Pole</u>	<u>S89°E</u>	<u>37.17*</u>

* distance to double head nail

N-21

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Sept. 1919; Twp rd order shows no survey

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____