


T. 138 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 24 Corner common to sections 13, 24 AND 18, 19, 138-29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>6"</u>	<u>5"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>N80E</u>	<u>N64W</u>	<u>S63/4W</u>	<u>S60E</u>
Distance	<u>26 LKS.</u>	<u>197 LKS.</u>	<u>58 LKS.</u>	<u>139 LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By JOHN Curo  
Location filed COUNTY SURVEY RECORD BOOK "B" P. 289-300  
Monument END IRON SET BY Curo

Evidence of Subsequent Corner Restoration

Year of search 1914 By Curo  
microfilm - roll 115 BK 92 P. 16  
Start W. from Iron Corner.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

N-25

Subsequent Corner Restoration

Year surveyed 10/92 By R. Morton #21401  
Location filed CCSO  
Monument Found 1 1/2" iron, 9.4' E. of E, 6' S. of E, down 0.6'. witness follow:

Evidence of Subsequent Corner Restoration Found

Year of search AUG. 2000 By CCSO  
Find. in place; pole nail placed in center on top of 2 1/2" ODIP, down 1.0' in N. Bound lane C.R. 42. Located 10' E & C.R. 42 & 3' South & Barclay Twp Rd. #4.

<u>7" Burr Oak</u>	<u>N35°E</u>	<u>135.33'</u>
<u>9" J. Pine</u>	<u>S38°E</u>	<u>111.88'</u>
<u>11" Burr Oak</u>	<u>S83°W</u>	<u>117.68'</u>

REF. TIES:

<u>(TAG) 6" W. Oak</u>	<u>N 40° E</u>	<u>135.66' (find nail)</u>
<u>6" R. Oak</u>	<u>S 41° E</u>	<u>96.47'</u>
<u>P.K. - S. End 15" CMP</u>	<u>S 63° W</u>	<u>61.48'</u>
<u>15" J. Pine</u>	<u>S 86° W</u>	<u>113.22' (find nail)</u>

Corner GPS 5/13/03 CCSO  
3/8" Rebar, down 0.1, 10' ± E. of E Co. Rd. #42, 3' ± S. of 12th st.

Aug. 1999 D. Landecker #17008  
Cert. of Sur. Shows mon. found