



T. 138 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 1 Corner common to sections 1 AND 6-138-30 AND 31-139-30
AND 36-139-31

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

| Species | Bearing | Trees | Distance |
|---------------|----------------|---------------|---------------|
| <u>ASPEN</u> | <u>N. Pine</u> | <u>ASPEN</u> | <u>ASPEN</u> |
| <u>12"</u> | <u>12"</u> | <u>12"</u> | <u>12"</u> |
| <u>N40E</u> | <u>N42W</u> | <u>S16W</u> | <u>S60E</u> |
| <u>69 LKS</u> | <u>28 LKS</u> | <u>81 LKS</u> | <u>37 LKS</u> |

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1921 By E. B. HORST

Location filed COUNTY RESURVEY "E-34"

Monument IRON MONUMENT AND GOVT BITS.

1920, BEN CLARK, BOOK "C" P. 426 FND CORNER.

1915, BALDWIN, BOOK "D" P. 20-21 FND CURO'S HUB: BITS.

4" W. BIRCH N65W 17.0' 3" OAK N52-30E 45.0' CURO SET CORNER

FROM N.W. B.T. SET I.P.

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|--|---------------------------|---------|----------|
| <u>1915 also on microfilm - roll 105 BK 53 P. 31</u> | <u>- P. 38 - set I.P.</u> | | |

Evidence of Subsequent Corner Restoration

Year of search 1939 By JOHN CURO

COUNTY BOOK "D" P. 232 FND 2498" I.P. SET PREVIOUSLY

FROM OLD U.S. B.T.S.

Bearing Trees, Reference Objects

| J. PINE | OAK | OAK | OAK |
|---------------|----------------|----------------|---------------|
| <u>11"</u> | <u>12"</u> | <u>7"</u> | <u>14"</u> |
| <u>N28E</u> | <u>N35-50W</u> | <u>S63-05W</u> | <u>S9-40E</u> |
| <u>37.35'</u> | <u>39.40'</u> | <u>27.65'</u> | <u>44.90'</u> |

(OVER)

A-25

Subsequent Corner Restoration

Year surveyed 1950 By HAROLD CURO

Location filed COUNTY BOOK "D" P. 352

Monument FND I.P. PREVIOUSLY ESTABLISHED FROM OLD

GOVT BITS. - STRAIGHT PIPE

TIES: 16" N. PINE N63-35E 75.00', 20" R. OAK S42-50E

79.55', 6" HARD MAPLE S40-10W 43.30', 16" R. OAK N29-44W

55.20'

1965, R.F. SCHNEIDER, BOOK "D" P. 439 FND CAPED I.P.

TIES: 14" R. OAK N29W 55.0', 12" J. PINE N27E 69.85'

16" N. PINE N64E 74.95'

1965-RFS - Survey for DNR - Map in file

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - ENGERS PINE MOUNTAIN BEACH

R.F. SCHNEIDER 1969

AUG. 2000 - CCSD

Fnd. in place; I.P. w/ plumbers cap

Found B.T. NE - Distance fits (1965 tie)

REF. TIES:

6" Maple N 15° W 20.81'

6" Ash S 53° W 30.12'

NW COR. GARAGE FOUND. - S 22° E 25.61'

16" N. PINE N 64° E 74.95' (exist B.T.)

Dec 2004 T Freeman # 21367

Cert. of Survey shows monument found