


T. 138 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 1 Corner common to sections 1 AND 6-138-31 AND 31-139-31
AND 36-139-32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1860
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

| Species | Bearing | Trees |
|------------------------|---------------|-----------------|
| <u>W. BIRCH</u> | <u>ASPEN</u> | <u>W. BIRCH</u> |
| <u>ASPEN</u> | | <u>ASPEN</u> |
| Diameter <u>10"</u> | <u>8"</u> | <u>6"</u> |
| Bearing <u>S30E</u> | <u>S75W</u> | <u>N60E</u> |
| Distance <u>11 LKS</u> | <u>28 LKS</u> | <u>32 LKS</u> |

Original Bearing Trees Found

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK "A" P 401
Monument FIND STAKE SET BY OLD CO. SURVEYOR JAMES
CANFIELD SET BY 8X8X36" CONCRETE POST
1916, E. B. HORST - BOOK "B" P. 561-563 FND
8X8X36" CONCRETE MONUMENT SET BY CURO
- also on microfilm - roll 105 BK 59 P 49

Evidence of Subsequent Corner Restoration

Year of search 1916 By JOHN CURO
COUNTY RESURVEY "E-48" 8X8X36" CONCRETE MONUMENT
COUNTY BOOK "C" P 402 CONCRETE MONUMENT - NO DATE

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 10-1893 By K. DONAHUE MN/DOT
Location filed CERT. OF LOCATION NO. 408853
Monument RAILROAD SPIKE IN BITUMINOUS IN & CO.
RD. #112, 2' SOUTH OF E T.H. #87

Evidence of Subsequent Corner Restoration Found

Year of search 2000 JUNE By CCSO
Fnd. in place; RR SPK - E.C.R. 112 &
2'S & TH BT. Fnd 2 B.T.'s w/ tags
NEW TIES:
P.K. in W. End 18" CMP N 32°W 31.47'
" " E. End 18" CMP N 30°E 31.86'

| | | |
|-------------------------------------|--------------|---------------|
| <u>SW COR HOUSE</u> | <u>N40°E</u> | <u>105.62</u> |
| <u>SE COR HOUSE</u> | <u>N50°E</u> | <u>129.20</u> |
| <u>NAIL & DISK COR FE. POST</u> | <u>S34°W</u> | <u>55.08</u> |
| <u>NAIL & DISK PEDESTAL</u> | <u>S68°E</u> | <u>75.53</u> |

Corner GPS CCSO 9/11/02
CCSO 9/11/02 Fd RR spike, down
0.1', 2' ± S. of E Hwy #87, 2'
E. of CR #112