


T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 3 Corner common to sections 2, 3 AND 34, 35- 140-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>	<u>SCRUB PINE</u>
Diameter	<u>10"</u>	<u>15"</u>	<u>15"</u>	<u>9"</u>
Bearing	<u>N 82E</u>	<u>N 75W</u>	<u>S 80W</u>	<u>S 33E</u>
Distance	<u>15 LKS</u>	<u>93 LKS</u>	<u>94 LKS</u>	<u>15 LKS.</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed T By Geo. A. RAHAT
Location filed COUNTY SURVEY RECORD BOOK B' P 90-91
Monument SURVEY OF STATE RURAL HWY # 83
TIES - SEE BOOK B' P 90-91

Evidence of Subsequent Corner Restoration

Year of search 1937 By CLL
Wagon Run Lake - BK# 1 P. 53
Find 2 1/2" lip w/ cap: 34/35 on E. EDGE
Small hay meadow 3/2
1938 BK# 20 P. 40 I.P. 100' west of Hwy 6

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

A-17

Subsequent Corner Restoration

Year surveyed 7/2002 By M. Stefan
Location filed _____
Monument 2" Iron pipe with steel cap
fence post along side. And
1998 Landecker witness trees.
A Certificate of Location was
filed

Evidence of Subsequent Corner Restoration Found

Year of search 1998 By Landecker
Found corner steel fence post
adjacent in pond
No. 1 & Cap 9" Birch N35°E 113.71
No. 1 & Cap 9" W. Oak S52°E 54.44
No. 1 & Cap 14" W. Oak S77°W 136.02

July 1930; J.H. Flynn
Trwp rd order shows corner