


T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 16 Corner common to sections 9, 10, 15, 16



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	MAPLE	MAPLE	PINE	W. PINE
Diameter	12"	12"	17"	24"
Bearing	N78E	S40E	S29W	N68W
Distance	36 LKS	8 LKS	92 LKS	92 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936? By CCC
Location filed Washburn Lake - BK# 3 P. 61
Monument Approx Cor 40 ch. east of 1/4 pt
1940 - CCC - BK# 8 - at 5280' from S - set approx
CORNER

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK# 9 - subdivision sec 16
at 5285' from S - yellow tag on N. line, 4" sq.
post (approx cor.)

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1-28-88 By John Walker / DNR
Location filed Cert. Filed Doc. # 312281
Monument Found 1 1/4" Iron pipe up 1'
Ties: 12" Red Oak N30E 5.8'; 12" Norway
Pine South 43'; Red Oak S45W 39.6'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SABIN'S EASTAUN ADDITION
DEAN ANDERSON 1957

1986 BUCKLER MAP SHOWS IN PLACE

J 13

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____