


T. 139 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 18 Corner common to sections 7, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Y. Pine</u>	<u>W. Pine</u>	_____
Diameter	<u>9"</u>	<u>10"</u>	_____
Bearing	<u>NORTH</u>	<u>SOUTH</u>	_____
Distance	<u>22 LKS</u>	<u>26 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936? By CCC  
Location filed Wasburn Lake - BK # 3 P. 41  
Monument End I.P.  
1938 - BK # 20 P. 41 - corner is 36' west of Lake George Road.

Evidence of Subsequent Corner Restoration

Year of search 1981 By DNR-Engineering  
Map notes in file  
End 1 1/2" I.P. w/ 2" metal cap  
49.6' W. of G Road

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>R. oak</u>	<u>Birch</u>	<u>R. oak</u>	<u>W. Full</u>
<u>8"</u>	<u>TRIPLE 5-10"</u>	<u>8"</u>	<u>gray rock</u>
<u>N30E</u>	<u>S80W</u>	<u>S5W</u>	<u>57x38x26"</u>
<u>41.83'</u>	<u>7.88'</u>	<u>28.00'</u>	<u>N70E</u>
			<u>16.00'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Bert Evdand - DNR - 1984  
same information as 1981 (over)  
Doc. # 279805

J3