

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. L 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X E 17417 Y 16,17
Corner common to sections 16,17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

| Species | Bearing | Trees |
|----------------|-----------------|-------|
| <u>W. PINE</u> | <u>W. BIRCH</u> | |
| <u>8"</u> | <u>6"</u> | |
| <u>S18W</u> | <u>S45E</u> | |
| <u>17 LKS</u> | <u>52 LKS</u> | |

Original Bearing Trees Found

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

O = Corner

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-10, E-11"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 313 SET 2x48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1982 By Co. SURVEYOR
FND 2 1/2" I.P. DOWN 0.2' 1" E. OF G. N-S RD
± 50' SOUTH OF N. EDGE CUTTING ON E. SIDE RD.
THERE IS A ± 36" W. PINE S58°E 138'

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|----------------|------------|----------------|---------------|
| <u>W. PINE</u> | <u>14"</u> | <u>S56-15W</u> | <u>152.1'</u> |
| <u>W. PINE</u> | <u>12"</u> | <u>N59-35E</u> | <u>138'</u> |

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|-----------------------|--------------------|---------------------|----------|
| <u>P.P.</u> | <u>ASPEN 4"</u> | <u>W. OAK 8"</u> | |
| <u>NAIL N.W. SIDE</u> | <u>NAIL NESIDE</u> | <u>NAIL S. SIDE</u> | |
| <u>N54°E</u> | <u>N50W</u> | <u>S75W</u> | |
| <u>37.02'</u> | <u>52.95'</u> | <u>48.35'</u> | |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Found R.R. spike, down 0.1'
1' ± E. of E. Co. Rd #174

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

| | | | |
|----------------------|--------------|---------------|--------------------|
| <u>1 1/2" W. Oak</u> | <u>N58°W</u> | <u>70.00'</u> | <u>dbl hd nail</u> |
| <u>W. Oak</u> | <u>S75°W</u> | <u>48.35'</u> | <u>10d nail</u> |
| <u>24" W. Pine</u> | <u>S58°E</u> | <u>138' ±</u> | |
| <u>P. Pole</u> | <u>N54°E</u> | <u>?</u> | <u>10d nail</u> |

May 1914; B. F. Clark
Trce rd order shows survey