


T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 3 Corner common to sections 2, 3



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. Pine</u>	<u>W. Pine</u>	_____
Diameter	<u>24"</u>	<u>15"</u>	_____
Bearing	<u>EAST</u>	<u>S67W</u>	_____
Distance	<u>104 LKS</u>	<u>116 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN Curo
Location filed COUNTY SURVEY RECORD BOOK B P. 200-211
Monument FIND OLD GWT BIT STUMP 24" N. PINE EAST
104 LKS

Evidence of Subsequent Corner Restoration

Year of search 1998 By Roger Mustonen
Corner shown as iron monument found
on certificate of survey. In road
East of E.

also on microfilm - roll 155 BK 271 P. 27

Bearing Trees, Reference Objects

Species	<u>PINE STUB</u>	<u>J. PINE</u>	_____
Diameter	<u>15"</u>	<u>6"</u>	_____
Bearing	<u>S56-30E</u>	<u>S30-18W</u>	_____
Distance	<u>31.85'</u>	<u>57.65'</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

C-17

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Lundecker - 1984 Doc # 276696
Find 1 1/2" I.P. - set Co. Cast iron down O.I.
Triple 10" Red Oak S75E 41.20'
16" N. Pine S25E 80.15'
10" W. Pine S30W 99.20'
7" N. Pine N75W 103.60'
in a N-S Hwy 84

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____