


T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 14 Corner common to sections 13, 14



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species TAM TAM.
 Diameter 6" 5"
 Bearing N 85 E N 50 W
 Distance 93.45 20.45

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 3/10/88 By Donn Rasmussen
 Found 1 1/4" iron pipe 3' above ground.
Old scar in 6" dead Tamarack S 80 E 54.10'
Old scar in 8" dead Tamarack S 81 W 53.00'

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

| | | | |
|-----------------|-----------------|-----------------|-----------------|
| <u>Tamarack</u> | <u>Tamarack</u> | <u>Tamarack</u> | <u>Tamarack</u> |
| <u>4"</u> | <u>3"</u> | <u>4"</u> | <u>4"</u> |
| <u>N 65 W</u> | <u>N 16 E</u> | <u>S 33 E</u> | <u>S 50 W</u> |
| <u>29.70'</u> | <u>69.90'</u> | <u>50.92'</u> | <u>38.00'</u> |

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - SHADYWOOD SHORES
HAROLD CURN 1952
8-18-88 Cert Filed by Donn Rasmussen
Doc # 366660.

L 21